

1/10

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7






FIG. 8

MPDU (MAC PROTOCOL DATA UNIT) - (2346 + 6) BYTES MAX MAC OUTPUT (802.11 + pad)



* MAC firmware latency causes extra non-valid TX data bits to be clocked out before TX mode can be shut down

PLCP FRAME FORMAT (PHYSICAL LAYER CONVERGENCE PROTOCOL)



6/10

FIG. 9




FIG. 10





FIG.



10/10

FIG. 12




FIG. 13

